

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/29/2016
FORM APPROVED
OMB NO. 0938-0381

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 445511	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN B. WING		(X3) DATE SURVEY COMPLETED 08/28/2016
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF COLETAH			STREET ADDRESS, CITY, STATE, ZIP CODE 6311 SNOW HILL ROAD COLETAH, TN 37363		
(X4) ID PREFIX TAG K 052 SS=F	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) NFPA 101 LIFE SAFETY CODE STANDARD A fire alarm system required for life safety shall be tested and maintained in accordance with NFPA 70 National Electric Code and NFPA 72 National Fire Alarm Code and records kept readily available. The system shall have an approved maintenance and testing program complying with applicable requirements of NFPA 70 and 72, 9.6.1.4, 9.6.1.7. This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure smoke detectors were at least 3-feet from air flow. The findings include: Observation and interview with the maintenance director, on 9/26/16 between 1:12 PM and 3:00 PM revealed smoke detectors in the following locations are within 3 feet of air flow: 1. Clean linen 300 hallway. 2. Janitor's closet on the 300 hallway. 3. Storage room by resident room 224. 4. Janitor's closet by resident room 101. 5. Soiled utility on the 100 hallway. (NFPA 101, 9.6.1.4, 9.6.1.7, NFPA 72, 2-3.5.1) These findings were verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/28/16.		ID PREFIX TAG K 052	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) 1) What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice. A licensed contractor relocated smoke detectors on 10/07/16 and 10/14/16 to ensure they were at least 3-feet from air flow. These locations included: 1. Clean linen 300 hallway. 2. Janitor's closet on the 300 hallway. 3. Storage room by resident room 224. 4. Janitor's closet by resident room 101. 5. Soiled utility on the 100 hallway. 2) How you will identify other residents having the potential to be affected by the same deficient practice and what corrective action will be taken. On 10/07/16 the Maintenance Director and a licensed contractor reviewed facility smoke detectors to ensure they were at least 3-feet from air flow. The licensed contractor relocated the smoke detector on 10/07/16 and 10/14/16 in four additional locations. These locations included: 1. Communication room on front hall. 2. Work room on front hall. 3. Storage room on 100 hall. 4. Clean utility room on 100 hall.	(X5) COMPLETION DATE 10/28/16
K 056 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD There is an automatic sprinkler system installed in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, with approved components, device and equipment, to provide		K 056		10/28/16

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Hanna Schum

TITLE

Executive Director

(X6) DATE

10/28/16

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings and plans of correction are due within 30 days following the date of survey. For nursing homes, the findings and plans of correction are due within 90 days following the date of survey. For all other facilities, the findings and plans of correction are due within 30 days following the date of survey. If deficiencies are cited, an approved plan of correction is required to be submitted.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/28/2016
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(K1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 445311	(K2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN B. WING		(K3) DATE SURVEY COMPLETED 09/28/2016
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF COOLTEWAH			STREET ADDRESS, CITY, STATE, ZIP CODE 6811 SNOW HILL ROAD COOLTEWAH, TN 37363		
(K4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(K5) COMPLETION DATE	
K 052 SS-F	<p>NFPA 101 LIFE SAFETY CODE STANDARD</p> <p>A fire alarm system required for life safety shall be tested, and maintained in accordance with NFPA 70 National Electric Code and NFPA 72 National Fire Alarm Code and records kept readily available. The system shall have an approved maintenance and testing program complying with applicable requirements of NFPA 70 and 72. 9.6.1.4, 9.6.1.7.</p> <p>This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure smoke detectors were at least 3-feet from air flow.</p> <p>The findings include:</p> <p>Observation and interview with the maintenance director, on 9/26/16 between 1:12 PM and 3:00 PM revealed smoke detectors in the following locations are within 3 feet of air flow:</p> <ol style="list-style-type: none"> 1. Clean linen 300 hallway. 2. Janitors closet on the 300 hallway. 3. Storage room by resident room 224. 4. Janitors closet by resident room 101. 5. Soiled utility on the 100 hallway. <p>(NFPA 101, 9.6.1.4, 9.6.1.7, NFPA 72, 2-3.5.1)</p> <p>These findings were verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/28/16.</p>	K 052	<p>K052 F Continued</p> <p>3) What measures will be put into place or what systematic changes you will make to ensure that the deficient practice does not recur.</p> <p>The Maintenance Director or designee will review facility smoke detectors monthly for three months to ensure they are at least 3-feet from air flow. Any modifications necessary following this review will be completed by a licensed contractor.</p> <p>4) How the corrective action(s) will be monitored to ensure the deficient practice will not recur.</p> <p>The Maintenance Director will present findings of the monthly smoke detector review to the facility Performance Improvement (PI) Committee. This committee consisting of the Executive Director, Director of Nursing, Medical Director, Director of Maintenance, Director of Rehab, Health Information Management Director, Director of Food and Nutrition Services, Director of Environmental Services, Director of Social Services, Business Office Manager, Director of Admissions and Director of Activities will review the</p>	10/28/16	
K 056 SS-D	<p>NFPA 101 LIFE SAFETY CODE STANDARD</p> <p>There is an automatic sprinkler system installed in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, with approved components, device and equipment, to provide</p>	K 056			

LABORATORY DIRECTOR OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Hiana Schless

TITLE

Executive Director

(K6) DATE

10/26/16

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting provided it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are actionable 30 days following the date of survey, whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are actionable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is required to conduct program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/28/2016
FORM APPROVED
OMB NO. 0938-0361

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 445511	(X2) MULTIPLE CONSTRUCTION A. BUILDING #1 - MAIN B. WING _____		(X3) DATE SURVEY COMPLETED 08/28/2016
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF COLTEWAH			STREET ADDRESS, CITY, STATE, ZIP CODE 6911 SNOW HILL ROAD COLTEWAH, TN 37363		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 052 SS=F	<p>NFPA 101 LIFE SAFETY CODE STANDARD</p> <p>A fire alarm system required for life safety shall be, tested, and maintained in accordance with NFPA 70 National Electric Code and NFPA 72 National Fire Alarm Code and records kept readily available. The system shall have an approved maintenance and testing program complying with applicable requirement of NFPA 70 and 72, 9.6.1.4, 9.6.1.7.</p> <p>This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure smoke detectors were at least 3-feet from air flow.</p> <p>The findings include:</p> <p>Observation and interview with the maintenance director, on 9/28/16 between 1:12 PM and 3:00 PM revealed smoke detectors in the following locations are within 3 feet of air flow:</p> <ol style="list-style-type: none"> 1. Clean linen 300 hallway. 2. Janitors closet on the 300 hallway. 3. Storage room by resident room 224. 4. Janitors closet by resident room 101. 5. Spilled utility on the 100 hallway. <p>(NFPA 101, 9.6.1.4, 9.6.1.7, NFPA 72, 2-3.6.1)</p> <p>These findings were verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/28/16.</p>	K 052	K052 F Continued findings and make recommendations and develop plans of action if any areas are noted to be non-compliant. This will occur monthly.	10/28/16	
K 056 SS=D	<p>NFPA 101 LIFE SAFETY CODE STANDARD</p> <p>There is an automatic sprinkler system installed in accordance with NFPA 13, Standard for the Installation of Sprinkler Systems, with approved components, device and equipment, to provide</p>	K 056	1) What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice.		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Hana Schless

TITLE

Executive Director

(X6) DATE

10/20/16

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See Instructions.) Except for nursing homes, the findings stated above are effective 30 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are effective 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is required to continue program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/29/2016
FORM APPROVED
OMB NO. 0938-0384

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(K1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 445511	(K2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN B. WING		(K3) DATE SURVEY COMPLETED 08/26/2016
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF COLTEWAH			STREET ADDRESS, CITY, STATE, ZIP CODE 5811 SNOW HILL ROAD COLTEWAH, TN 37363		
(K4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(K5) COMPLETION DATE	
K 056	Continued From page 1 complete coverage of all portions of the facility. Systems are equipped with waterflow and tamper switches, which are connected to the fire alarm system. In Type I and II construction, alternative protection measures shall be permitted to be substituted for sprinkler protection in specific areas where State or local regulations prohibit sprinklers. 18.3.5, 18.3.5.1. This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure all areas were sprinkled. The findings include: Observation and interview with the maintenance director, on 9/28/16 at 1:06 PM revealed the electrical room on the 300 hallway does not have sprinkler coverage. Facility sprinkler blue prints show sprinkler coverage in this room. (NFPA 101, 18.3.5, 18.3.5.1, 9.7, NFPA 13, 5-1.1) This finding was verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/28/16.	K 056	K056 D Continued A licensed contractor installed a sprinkler head in the electrical room on the 300 hallway on 10/20/16. 2) How you will identify other residents having the potential to be affected by the same deficient practice and what corrective action will be taken. On 10/14/16 the Maintenance Director and Executive Director reviewed the facility to ensure all areas are sprinkled. A licensed contractor will install a sprinkler head on 300 hall on 10/20/16. 3) What measure will be put into place or what systematic changes you will make to ensure that the deficient practice does not recur. The Maintenance Director or designee will review facility sprinkler system monthly to ensure all areas of the facility are sprinkled. Any modifications necessary following this review will be completed by a licensed contractor. 4) How the corrective action(s) will be monitored to ensure the deficient practice will not recur. The Maintenance Director will present findings of the monthly smoke detector review to the facility Performance	10/28/16	
K 062 SS=F	NFPA 101 LIFE SAFETY CODE STANDARD Automatic sprinkler systems are continuously maintained in reliable operating condition and are inspected and tested periodically. 18.7.6, 19.7.6, 4.6.12, NFPA 13, NFPA 25, 9.7.5 This STANDARD is not met as evidenced by: Based on record review, the facility failed to ensure the sprinkler system was maintained in reliable operating condition. The findings include:	K 062		10/28/16	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/29/2016
FORM APPROVED
OMB NO. 0938-0301

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(K1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 445511	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN B. WING _____		(X3) DATE SURVEY COMPLETED 03/29/2016
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF COOLTEWAH			STREET ADDRESS, CITY, STATE, ZIP CODE 0011 SNOW HILL ROAD COOLTEWAH, TN 37363		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 058	Continued From page 1 complete coverage of all portions of the facility. Systems are equipped with waterflow and tamper switches, which are connected to the fire alarm system. In Type I and II construction, alternative protection measures shall be permitted to be substituted for sprinkler protection in specific areas where State or local regulations prohibit sprinklers. 18.3.5, 18.3.5.1. This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure all areas were sprinkled. The findings include: Observation and interview with the maintenance director, on 9/28/16 at 1:08 PM revealed the electrical room on the 300 hallway does not have sprinkler coverage. Facility sprinkler blue prints show sprinkler coverage in this room. (NFPA 101, 18.3.5, 18.3.5.1, 9.7, NFPA 13, 5-1.1) This finding was verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/28/16.	K 056	K056D Continued Improvement (PI) Committee. The committee consisting of the Executive Director, Director of Nursing, Medical Director, Director of Maintenance, Director of Rehab, Health Information Management Director, Director of Food and Nutrition Services, Director of Environmental Services, Director of Social Services, Business Office Manager, Director of Admissions, and Director of Activities will review the findings and make recommendations and develop plans of action if any areas are noted to be non-compliant. This will occur monthly.	10/28/16	
K 062 SS-F	NFPA 101 LIFE SAFETY CODE STANDARD Automatic sprinkler systems are continuously maintained in reliable operating condition and are inspected and tested periodically. 18.7.6, 19.7.6, 4.6.12, NFPA 13, NFPA 25, 9.7.5 This STANDARD is not met as evidenced by: Based on record review, the facility failed to ensure the sprinkler system was maintained in reliable operating condition. The findings include:	K 062			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/29/2016
FORM APPROVED
OMB NO. 0938-0361

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(K1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 445511	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN B. WING _____		(X3) DATE SURVEY COMPLETED 09/26/2016
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF COLTEWAH			STREET ADDRESS, CITY, STATE, ZIP CODE 5911 SNOW HILL ROAD COLTEWAH, TN 37363		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 056	Continued From page 1 complete coverage of all portions of the facility. Systems are equipped with water flow and tamper switches, which are connected to the fire alarm system. In Type I and II construction, alternative protection measures shall be permitted to be substituted for sprinkler protection in specific areas where State or local regulations prohibit sprinklers. 18.3.5, 18.3.5.1. This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure all areas were sprinkled. The findings include: Observation and interview with the maintenance director, on 9/26/16 at 1:06 PM revealed the electrical room on the 300 hallway does not have sprinkler coverage. Facility sprinkler blue prints show sprinkler coverage in this room. (NFPA 101, 18.3.5, 18.3.5.1, 9.7, NFPA 13, 5-1.1) This finding was verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/26/16.	K 056			
K 052 SS-F	NFPA 101 LIFE SAFETY CODE STANDARD Automatic sprinkler systems are continuously maintained in reliable operating condition and are inspected and tested periodically. 18.7.6, 19.7.6, 4.6.12, NFPA 13, NFPA 25, 9.7.5 This STANDARD is not met as evidenced by: Based on record review, the facility failed to ensure the sprinkler system was maintained in reliable operating condition. The findings include:	K 052	1) What corrective action(s) will be accomplished for those residents found to have been affected by the deficient practice.		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/29/2016
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(K1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 445511	(K2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN B. WING _____		(K3) DATE SURVEY COMPLETED 09/28/2016
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF COLTEWAH			STREET ADDRESS, CITY, STATE, ZIP CODE 5911 SNOW HILL ROAD COLTEWAH, TN 37383		
(K4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(K5) COMPLETION DATE	
K 062	Continued From page 2 Record review with the maintenance director, on 8/26/16 at 10:33 AM revealed during the 3 year full flow trip test on system #2 water reached the inspectors testing location in 1 minute and 10 seconds. (NFPA 101, 18.7.6, 4.8.12, 9.7.5, NFPA 13, 4-2.4.1) This finding was verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/26/16.	K 062	K062 F Continued A licensed contractor conducted the 3-year full flow trip test on the dry sprinkler system #2. Water reached the inspector's testing location in 54 seconds on 10/13/16. A licensed contractor conducted a second 3-year full flow trip test on the dry sprinkler system #2. Water reached the inspector's testing location in 50 seconds on 10/20/16. Based on the results of both tests, the facility has ensured the sprinkler system is maintained in reliable operating condition. 2) How will you identify other residents having the potential to be affected by the same deficient practice and what corrective action(s) will be taken. A licensed contractor retested the required 3-year full flow drip test on the dry sprinkler system #2 and the results confirmed the sprinkler system is maintained in reliable operating condition on 10/13/16.	10/28/16	10/28/16

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/29/2016
FORM APPROVED
OMB NO. 0938-0301

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 445511	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN B. WING		(X3) DATE SURVEY COMPLETED 09/28/2016
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF COLTEWAH			STREET ADDRESS, CITY, STATE, ZIP CODE 5911 SNOW HILL ROAD COLTEWAH, TN 37363		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 062	Continued From page 2 Record review with the maintenance director, on 9/26/16 at 10:33 AM revealed during the 3 year full flow trip test on system #2 water reached the inspectors testing location in 1 minute and 10 seconds. (NFPA 101, 18.7.6, 4.6.12, 9.7.5, NFPA 13, 4-2.4.1) This finding was verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/26/16.	K 062	K062 Continued 3) What measures will be put into place or what systematic changes you will make to ensure that the deficient practice does not recur. The facility will utilize a licensed contractor to complete the 3-year full flow trip test on the dry sprinkler system on or before 06/09/2019. 4) How the corrective actions(s) will be monitored to ensure the deficient practice will not recur. The Maintenance Director will present the findings of the 3-year full flow trip test on dry sprinkler system #2 to the facility Performance Improvement (PI) Committee. This committee consisting of the Executive Director, Director of Nursing, Medical Director, Director of Maintenance, Director of Rehab, Health Information Management Director, Director of Food and Nutrition Services, Director of Environmental Services, Director of Social Services, Business Office Manager, Director of Admissions, and Director of Activities will review the findings and make recommendations and develop	10/28/16	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/29/2016
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(K1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: A45611	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN B. WING		(X3) DATE SURVEY COMPLETED 09/26/2016
NAME OF PROVIDER OR SUPPLIER LIFE CARE CENTER OF COLTEWAH			STREET ADDRESS, CITY, STATE, ZIP CODE 5911 SNOW HILL ROAD COLTEWAH, TN 37363		
(K4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(K5) COMPLETION DATE	
K 062	Continued From page 2 Record review with the maintenance director, on 9/26/16 at 10:33 AM revealed during the 3 year full flow trip test on system #2 water reached the inspectors testing location in 1 minute and 10 seconds. (NFPA 101, 18.7.8, 4.8.12, 9.7.6, NFPA 13, 4-2.4.1) This finding was verified by the maintenance director and acknowledged by the administrator and corporate during the exit conference on 9/26/16.	K 062	K062 F Continued plans of action if any areas are noted to be non-compliant. This will occur monthly.	10/28/16	